



8 March 2021

Part Discontinuation Notice

Effective immediately, the part number(s) listed below are no longer being offered by Magnetix. Last time buy orders only will be accepted only if the product(s) are currently in stock. New orders will not be accepted.

Part Number(s) Discontinued	Recommended Replacement(s)
0AC522423	None

We appreciate your business and regret any inconvenience caused.

Please contact your Magnetix Sales Engineer or Customer Service Representative, or email magnetix@spang.com, with questions or concerns.