



25 June 2020

Part Discontinuation Notice

Effective immediately, the part number(s) listed below are no longer being offered by Magnetics. Last time buy orders only will be accepted only if the product(s) are currently in stock. New orders will not be accepted.

Part Number(s) Discontinued	Recommended Replacement(s)
0BC703540	None

We appreciate your business and regret any inconvenience caused.

Please contact your Magnetics Sales Engineer or Customer Service Representative, or email magnetics@spang.com, with questions or concerns.