

21 February 2019 Updated 4 May 2020

Part Discontinuation Notice

Effective immediately, the part number(s) listed below are no longer being offered by Magnetics. Last time buy orders only will be accepted only if the product(s) are currently in stock. New orders will not be accepted.

Part Number(s) Discontinued	Recommended Replacement(s)
PCB2318T1	PCB2318TA
PCB2318B1	PCB2318TA

We appreciate your business and regret any inconvenience caused.

Please contact your Magnetics Sales Engineer or Customer Service Representative, or email magnetics@spang.com, with questions or concerns.